

HIGH COLLISION CORRIDORS


1. East Market Street
2. Williams Road
3. East Laurel Drive
4. Boronda Road
5. East Alisal Street
6. North Main Street
7. West Laurel Drive
8. North Sanborn Road
9. E. Laurel Drive
10. Sanborn Road




COLLISION CORRIDORS

East Market Street, from Sherwood Drive to North Sanborn Road: 2009- 2018

NOTABLE PRIMARY COLLISION FACTORS




NOTABLE COLLISION TYPES



COLLISION CORRIDORS

Williams Road, from East Alisal Street to East Boronda Road: 2009- 2018

NOTABLE PRIMARY COLLISION FACTORS



AUTO R/W
VIOLATION
27%



UNSAFE
SPEED
16%




IMPROPER
TURNING
14%



DUI
11%

COLLISION TYPES



COLLISION CORRIDORS

East Laurel Drive, from Natividad Road to North Sanborn Road: 2009- 2018

NOTABLE PRIMARY COLLISION FACTORS




UNSAFE
SPEED
40%



DUI
12%

COLLISION TYPES



COLLISION CORRIDORS

Boronda Road, from US 101 to Natividad Road: 2009- 2018

NOTABLE PRIMARY COLLISION FACTORS



UNSAFE
SPEED
44%





IMPROPER
TURNING
8%



TRAFFIC SIGNALS
& SIGNS
8%


COLLISION TYPES




COLLISION CORRIDORS

East Alisal Street, from Front Street to North Sanborn Road: 2009- 2018

NOTABLE PRIMARY COLLISION FACTORS



COLLISION TYPES




COLLISION CORRIDORS

North Main Street, from Market Street to Casentini Street: 2009- 2018

NOTABLE PRIMARY COLLISION FACTORS



COLLISION TYPES



COLLISION CORRIDORS

West Laurel Drive, from North Davis Road to North Main Street: 2009- 2018

NOTABLE PRIMARY COLLISION FACTORS



UNSAFE
SPEED
25%



TRAFFIC SIGNALS
& SIGNS
19%





AUTO R/W
VIOLATION
12%



IMPROPER
TURNING
10%

COLLISION TYPES



COLLISION CORRIDORS

North Sanborn Road, from Del Monte Ave to East Boronda Road: 2009- 2018

NOTABLE PRIMARY COLLISION FACTORS



AUTO R/W
VIOLATION
46%



TRAFFIC SIGNALS
& SIGNS
14%




UNSAFE
SPEED
11%



IMPROPER
TURNING
8%

COLLISION TYPES



COLLISION CORRIDORS

East Laurel Drive, from North Main Street to Natividad Road: 2009- 2018

NOTABLE PRIMARY COLLISION FACTORS



IMPROPER
TURNING
11%




AUTO R/W
VIOLATION
21%



UNSAFE
SPEED
25%

COLLISION TYPES




COLLISION CORRIDORS

Sanborn Road, from US Highway 101 to East Laurel Drive: 2009- 2018

NOTABLE PRIMARY COLLISION FACTORS



UNSAFE
SPEED
26%



AUTO R/W
VIOLATION
18%



TRAFFIC SIGNALS
& SIGNS
12%

COLLISION TYPES

