

City of Salinas – Sanitary Sewer System Photographs

Images 1 & 2. Clogged Pipe



Image 3. Detached Pipe at Lift Station



Image 4. Joint Offset



Image 5. Broken Pipe




Image 6. Grease & Fat Buildup in Pipe



Image 7. Sewer Main Repair



Image 8. Sewer Bypass for Sewer Main Replacement

